ENGINE MAINTENANCE GUIDELINES - 200V SERIES MIDMOUNT™ UNITS

This is intended as a general reference guide. Consult your engine manual for complete service details. 200V SERIES USES VERTICAL CRANKSHAFT, OHV, PRESSURE LUBE/FILTER ENGINES

AIR-COOLED MODELS, VERTICAL SHAFT, V-TWIN, GASOLINE

Model 225V (25 hp - 747 cc) - Kohler Confidant Series Model 226V (26 hp - 810 cc) - B&S Commercial Turf Series Model 227V EFI (27 hp - 747 cc) - Kohler Confidant EFI Series

Engine Oil:

Break-in change oil & filter: 5 Hours, then:

Oil Change Intervals:

Oil Filter Order Number:

225V/227V EFI: Change oil & filter every 100 hours* 225V/227V EFI – 100802

226V: Change oil & filter every 50 hours 226V – 100803

Oil Type:

API Service Class: SJ or higher 2 quarts (1.9 liters)

Viscosity Recommendations:

SAE 30 wt. (above 40° F); 10W-30 ($0^{\circ} - 100^{\circ}$ F)

For extreme hot or cold operating temperatures, see engine manual for other viscosity recommendations.

Air Filters:

Replace pre-cleaners (outer elements) every 25 hours or more often in dusty conditions.

225V/227V EFI: 100916 – Pre-cleaner; 100917 Air Filter-Kohler – replace at 100-hour intervals

226V: S/N 6199999 & below: 100918 - cartridge with foam pre-cleaner - replace at 25-hour intervals

226V: S/N 6200000 & above: 100919 – canister cartridge – replace at 250 hours, or annually.

CAUTION: Use OEM filters only. Some aftermarket filters do not have adequate sealing characteristics and may have irregular dimensions or specifications in their filter-media composition. An incorrect size filter allows contaminants into the engine's system, voiding warranty and possibly resulting in engine damage or failure.

Spark Plugs & Fuel Filter Information		
	Kohler Confidant Series (includes EFI)	B&S Commercial Turf Series
Spark Plugs (Check at 100 hours)	Champion RC12YC	Champion RC12YC
Fuel Filter (Replace annually)	101001	366560

Contact Information:

Your Grasshopper dealership should always be the first place to call with questions about your Grasshopper To contact engine manufacturers directly, try calling:

Briggs & Stratton: 800-233-3723

Kohler: 800-544-2444

^{*} In severe conditions, such as high heat or heavy dust & debris, reduce change interval to 50 hours.